

OKLAHOMA DEPARTMENT OF TRANSPORTATION - Bridge Inspection Report

NBI No.: **12934** Structure No.: 6702 0543 X Local ID:-1

Suff. Rating: 84.3
ND

Health Index :
75.0

Inspection Date: 1/29/2018 Reported By: UFD3012
Invoice No.: -1 Inspected With: Erik Cox
Agency :

Structure / Inspection Notes

HISTORY TWO STEEL PIPLINES CROSS N. CHAN APPR 20' FROM BOX.

#61 ABC&D (FX) UPSTREAM CHAN IS HITTING N-W WING - CHAN NEEDS TO BE OPENED, REDIRECTED & PROTECTED. #223 GUTTERS NEED CLEANOUT.

Elem.	Env.	Description	Un.	Qty.	Qty.St. 1	% 1	Qty.St. 2	% 2	Qty.St. 3	% 3	Qty.St. 4	% 4	Qty.St. 5	% 5
241	1	Reinforced Concrete Culvert	(LF)	131	47	36 %	67	51 %	17	13 %	0	0 %	0	0 %
331	1	Reinforced Conc Bridge Railing	(LF)	66	51	77 %	15	23 %	0	0 %	0	0 %	0	0 %
960	1	Settlement	(EA)	1	0	0 %	1	100 %	0	0 %	0	0 %	0	0 %

Additional Elements

Elem.	Element Notes (Include Size and Location of Deterioration)
241	PX- APPROX. 1.5" WIDE CRACKS IN W. BBL FROM APRON FLOOR UP & INTO BBL. 5' N. END OF BOX, E. BBL. , S. END 15' INTO BBL. THERE IS A 1" OPEN CRACK IN E. WALL, TO TOP OF BBL. & TO CTR. BBL. WALL ALSO, LEACHING THRU S. HDWL & TOP OF BOX.
331	PX- RUSTING & CRACKING TO CONNECTION @ HDWLS, N. RAIL IS 3" OUT OF VERTICAL ALIGNMENT.
960	PX- NO CHANGE SINCE LAST INSP.